

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/8/2013	<b>Time:</b>	9:49 AM
<b>Name of School Corporation:</b>	SOUTHERN HANCOCK COMM. SCHOOLS			<b>Corp ID:</b>	303115
<b>Address of School Corporation:</b>	PO Box 508				
<b>City:</b>	New Palistine	<b>Zip:</b>	46163	<b>County Number:</b>	30
<b>VIN:</b>	1HVBBABP93H549621	<b>License Number:</b>	MOSB3987	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2003	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	John Pang	<b>PE:</b>	6196

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-8	The electric power assist motor fails to operate.
21-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**