# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 5/9/2013 | **Time:** | 12:30 PM |
| **Name of School Corporation:** | BREMEN PUBLIC SCHOOLS | | | **Corp ID:** | 505480 |
| **Address of School Corporation:** | 512 W Grant St | | | | |
| **City:** | Breman | **Zip:** | 46506 | **County Number:** | 50 |
| **VIN:** | 1GB3GSBG5G1142464 | **License Number:** | temp272722 | **Bus Number:** | 17 |
| **Make of Body:** | Chevrolet **Year:** 2017 | **Make of Chassis:** | Thomas Built Buses, Inc. | **Year:** | 2017 |
| **Bus Type:** | A2 | **Mileage:** | Unknown | | |
| **Inspection Status:** | A | **Inspected By:** | Travis Harrold | **PE:** | 8022 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**