# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/13/2013 Time: 1:27 PM Name of School Corporation: RIVER FOREST COMM. SCHOOL CORP Corp ID: 454590

Address of School Corporation: 3250 Michigan St

City:HobartZip:46342County Number:45VIN:1HVBJABP01A911831License Number:18963Bus Number:7Make of Body:IC Corporation Year:2001Make of Chassis:IC Corporation Year:2001

Bus Type: D Mileage: Unknown

Inspection Status: O Inspected By: Nathan Sherer PE: 7029

### **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

22-1-5 Any hanger, clamp or bracket is missing, loose or broken.

#### **Violations - Out of Service**

### <u>Inspection Code</u> <u>Description</u>

8-2-8 The electric power assist motor fails to operate.

### **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.