

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 5/13/2013 **Time:** 11:58 AM
Name of School Corporation: RIVER FOREST COMM. SCHOOL CORP **Corp ID:** 454590
Address of School Corporation: 3250 Michigan St
City: Hobart **Zip:** 46342 **County Number:** 45
VIN: 4DRBUAAN49B127621 **License Number:** 32149 **Bus Number:** 16
Make of Body: IC Corporation **Year:** 2009 **Make of Chassis:** IC Corporation **Year:** 2009
Bus Type: C **Mileage:** Unknown
Inspection Status: R **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
67-1-1	Washers do not function properly in any manner

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.