

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/7/2013	Time:	10:34 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	Zip:	47140	County Number:	13
VIN:	1GDL7T1C8XJ515850	License Number:	B931B	Bus Number:	17
Make of Body:	Blue Bird Corporation	Year:	2000	Make of Chassis:	GMC
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-4	Rear tire has less than 2/32 inch tread depth when measured in a major groove.
19-1-8	If required, positive door opening device is missing or fails to operate properly.
69-1-7	Emergency window is too difficult to open

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.