REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	5/6/2013	**Time:**	10:05 AM
Name of School Corporation:	NORTHEAST DUBOIS CO. SCH. CORP					**Corp ID:**	192040
Address of School Corporation:	5379 E Main St						
City:	Dubois		**Zip:**	47527		**County Number:**	19
VIN:	1HVBBAAP8XH252444			**License Number:**	B487D	**Bus Number:**	13
Make of Body:	IC Corporation	**Year:**	1999	**Make of Chassis:**	IC Corporation	**Year:**	1999
Bus Type:	C			**Mileage:**	Unknown		
Inspection Status:	O		**Inspected By:**	Travis Coryea		**PE:**	5892

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
31-2-1	There is fuel leaking from any point on the fuel system.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.