REPORT OF SCHOOL BUS INSPECTION

Type of 12:58 5/14/2013 **Time**: Annual Date: Inspection: РМ NORTH DAVIESS CO. COMM. SCHOOL Name of School Corporation: 141375 Corp ID: **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 1GDL7T1D8XJ517185 B590C **Bus Number:** 11 Number: Make of Blue Bird Year: 2000 GMC 2000 Make of Body: Year: Corporation Chassis: Bus Type: С Mileage: Unknown Inspected PE: **Inspection Status:** O Travis Coryea 5892 By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

4-1-1 Any body clamp is loose.

Violations - Out of Service

Inspection
Code

22-2-1

Description

Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.