

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/14/2013	Time:	12:51 PM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4DRBRABP13A955902	License Number:	B208E	Bus Number:	6
Make of Body:	IC Corporation	Year:	2003	Make of Chassis:	IC Corporation
		Year:		Year:	2003
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
40-1-4	There is debris in the bus. (needs cleaned) includes dirt
24-1-1	Mirror or mirror backs are loose or improperly mounted.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	There is fuel leaking from any point on the fuel system.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.