

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/14/2013 Time: 12:51 PM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375
Address of School Corporation: 5494 E SR 58
City: El Nora Zip: 47529 County Number: 14
VIN: 4DRBRABP13A955902 License Number: B208E Bus Number: 6
Make of Body: IC Corporation Year: 2003 Make of Chassis: IC Corporation Year: 2003
Bus Type: C Mileage: Unknown
Inspection Status: O Inspected By: Travis Coryea PE: 5892

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 40-1-4 | There is debris in the bus. (needs cleaned) includes dirt |
| 24-1-1 | Mirror or mirror backs are loose or improperly mounted. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 31-2-1 | There is fuel leaking from any point on the fuel system. |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.