

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Spot Checks	<b>Date:</b> 5/14/2013	<b>Time:</b> 12:33 PM	
<b>Name of School Corporation:</b> NORTH DAVIESS CO. COMM. SCHOOL	<b>Corp ID:</b> 141375		
<b>Address of School Corporation:</b> 5494 E SR 58			
<b>City:</b> Elnora	<b>Zip:</b> 47529	<b>County Number:</b> 14	
<b>VIN:</b> 1HVBBAAP9XH204676	<b>License Number:</b> B377D	<b>Bus Number:</b> 16	
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 1999
<b>Bus Type:</b> C	<b>Mileage:</b> Unknown		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Coryea	<b>PE:</b> 5892	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
43-1-1	Marker light or lens is missing, cracked, faded, wrong color, or inoperative.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
45-2-2	Seat is broken or not attached to the floor.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**