

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/15/2013	<b>Time:</b>	10:33 AM
<b>Name of School Corporation:</b>	MISSISSINEWA COMM. SCHOOL CORP			<b>Corp ID:</b>	272855
<b>Address of School Corporation:</b>	424 E South A St				
<b>City:</b>	Gas City	<b>Zip:</b>	46933	<b>County Number:</b>	27
<b>VIN:</b>	1T88S4E1191113694	<b>License Number:</b>	31611	<b>Bus Number:</b>	12
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	Unknown	<b>Year:</b>	2009
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
45-1-2	Seat back or bottom is loose.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, the certification has expired, or is not signed within the six month requirement.
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.