

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/15/2013	<b>Time:</b>	9:38 AM
<b>Name of School Corporation:</b>	CENTERVILLE-ABINGTON COMM SCHS			<b>Corp ID:</b>	898360
<b>Address of School Corporation:</b>	116 W SOUTH ST				
<b>City:</b>	CENTERVILLE	<b>Zip:</b>	47330	<b>County Number:</b>	89
<b>VIN:</b>	4UZAAXCT55CN82565	<b>License Number:</b>	20426	<b>Bus Number:</b>	M3
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2005	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2004
<b>Bus Type:</b>	B	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Eric Thumb	<b>PE:</b>	5982

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Paint is badly faded or peeling.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
40-2-1	Interior is excessively dirty. (Excessive trash or dirt)

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**