

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 5/15/2013 **Time:** 1:08 PM  
**Name of School Corporation:** VINCENNES COMM. SCHOOL CORP.      **Corp ID:** 424335  
**Address of School Corporation:** 1712 S Hart St Rd  
**City:** Vincennes      **Zip:** 47591      **County Number:** 42  
**VIN:** 1GBHG31V361211856      **License Number:** 70097      **Bus Number:** 109  
**Make of Body:** Mid Bus, Inc. **Year:** 2006      **Make of Chassis:** Chevrolet **Year:** 2006  
**Bus Type:**      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Chuck Tharp      **PE:** 5618

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
25-1-2	Not fully charged
23-1-5	Paint is badly faded or peeling.

## Violations - Out of Service

## Inspection Code Description

### Bus Type Description