

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/20/2013 Time: 11:59 AM
Name of School Corporation: TRI-CAP EOC, INC Corp ID: 19001Z
Address of School Corporation: PO Box 729
City: Jasper Zip: 47546 County Number: 19
VIN: 1GBHG31R8W1089739 License Number: 16334 Bus Number: 7
Make of Body: Mid Bus, Inc. Year: 1998 Make of Chassis: Chevrolet Year: 1998
Bus Type: A1 Mileage: Unknown
Inspection Status: O Inspected By: Kelly Hammond PE: 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.