

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/20/2013	<b>Time:</b> 9:42 AM
<b>Name of School Corporation:</b> BEECH GROVE COMM SCHLS	<b>Corp ID:</b> 495380	
<b>Address of School Corporation:</b> 5334 Hornet Ave		
<b>City:</b> Beech Grove	<b>Zip:</b> 46107	<b>County Number:</b> 49
<b>VIN:</b> 4DRBWAAR0AA195969	<b>License Number:</b> 32886	<b>Bus Number:</b> 2
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2010	<b>Mileage:</b> Unknown	<b>Year:</b> 2010
<b>Bus Type:</b> D		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Chris Kath	<b>PE:</b> 6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
21-1-1	A dripping oil or fluid leak.
43-1-1	Marker light or lens is missing, cracked, faded, wrong color, or inoperative.
16-1-1	Dome light is inoperative.
19-1-8	If required, positive door opening device is missing or fails to operate properly.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**