

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/23/2013	<b>Time:</b>	9:56 AM
<b>Name of School Corporation:</b>	SOUTH HARRISON COMM. SCH. CORP			<b>Corp ID:</b>	313190
<b>Address of School Corporation:</b>	315 S Harrison Dr				
<b>City:</b>	Corydon	<b>Zip:</b>	47112	<b>County Number:</b>	31
<b>VIN:</b>	1HVBBAAP1XH201819	<b>License Number:</b>	B811G	<b>Bus Number:</b>	12
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	1999	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown	<b>Year:</b>	1999
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Troy Boyd	<b>PE:</b>	5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
62-1-4	Rear tire has less than 2/32 inch tread depth when measured in a major groove.
16-1-1	Dome light is inoperative.
68-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-3	Tire is flat

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**