REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/23/2013 Time: 10:55 AM Name of School Corporation: SHELBY EASTERN SCHOOLS Corp ID: 737285

Address of School Corporation: 2451 N 600 E

City:ShelbyvilleZip:46176County Number:73VIN:1HVBBABP1HX208770License Number:Bus Number:17Make of Body:AmTran Year:1999Make of Chassis:IC Corporation Year:1999

Bus Type: D Mileage: Unknown

Inspection Status: O Inspected By: Chris Clark PE: 6665

Violations - Rejected

Inspection Code	<u>Description</u>
23-1-5	Paint is badly faded or peeling.
19-1-3	The handle guard is missing or bent.
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.