# REPORT OF SCHOOL BUS INSPECTION

Type of 8:56 Time: Annual Date: 5/24/2013 Inspection: ΑM Name of School Corporation: SHELBY EASTERN SCHOOLS Corp ID: 737285 **Address of School Corporation:** 2451 N 600 E County City: Shelbyville Zip: 46176 73 Number: License VIN: 1HVBBABP9XH204630 B488B **Bus Number:** Number: Make of IC Blue Bird **Year:** 1999 Make of Body: Year: 1999 Corporation Corporation Chassis: **Bus Type:** D Mileage: Unknown Inspected PE: **Inspection Status:** O Chris Clark 6665 By:

## **Violations - Rejected**

Inspection Code	<u>Description</u>
23-1-5	Paint is badly faded or peeling.
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
39-1-2	Required instrument or gauge is inoperative.

#### **Violations - Out of Service**

## **Inspection Code Description**

### **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.