REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/12/2013	**Time:**	8:13 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP			**Corp ID:**	616260
Address of School Corporation:	RR 1				
City:	Montezuma	**Zip:**	47862	**County Number:**	61
VIN:	4DRBUAAP6DB163921	**License Number:**	14643	**Bus Number:**	SWP14
Make of Body:	IC Corporation **Year:** 2013	**Make of Chassis:**	IC Corporation	**Year:**	2013
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Chuck Tharp	**PE:**	5618

Violations - Rejected

Inspection Code	Description
27-1-2	The first aid kit is not properly filled.
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
14-1-2	A defroster motor is inoperative at any speed.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.