

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/12/2013	Time: 8:13 AM
Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP	Corp ID: 616260	
Address of School Corporation: RR 1		
City: Montezuma	Zip: 47862	County Number: 61
VIN: 4DRBUAAP6DB163921	License Number: 14643	Bus Number: SWP14
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation
Year: 2013	Mileage: Unknown	Year: 2013
Bus Type: C		
Inspection Status: R	Inspected By: Chuck Tharp	PE: 5618

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
14-1-2	A defroster motor is inoperative at any speed.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.