

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                         |                        |            |                         |           |              |      |
|---------------------------------------|-------------------------|------------------------|------------|-------------------------|-----------|--------------|------|
| <b>Type of Inspection:</b>            | Annual                  | <b>Date:</b>           | 6/13/2013  | <b>Time:</b>            | 10:50 AM  |              |      |
| <b>Name of School Corporation:</b>    | AREA 30 CAREER CENTER   | <b>Corp ID:</b>        | 676000     |                         |           |              |      |
| <b>Address of School Corporation:</b> | 1 N Calbert Way Suite A |                        |            |                         |           |              |      |
| <b>City:</b>                          | Greencastle             | <b>Zip:</b>            | 46135      | <b>County Number:</b>   | 67        |              |      |
| <b>VIN:</b>                           | 1GBHG31FX11128958       | <b>License Number:</b> | 65723      | <b>Bus Number:</b>      | 3         |              |      |
| <b>Make of Body:</b>                  | Collins Bus Corporation | <b>Year:</b>           | 2001       | <b>Make of Chassis:</b> | Chevrolet | <b>Year:</b> | 2001 |
| <b>Bus Type:</b>                      |                         | <b>Mileage:</b>        | Unknown    |                         |           |              |      |
| <b>Inspection Status:</b>             | <input type="radio"/>   | <b>Inspected By:</b>   | Mark Raper | <b>PE:</b>              | 6473      |              |      |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                    |
|------------------------|---|
| 54-2-3                 | Any steering component jams or inhibits safe movement |
| 8-2-5                  | There is brake fluid leaking at any point.            |

#### Bus Type Description