

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/14/2013	Time:	9:28 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP	Corp ID:	616260		
Address of School Corporation:	RR 1				
City:	Montezuma	Zip:	47862	County Number:	61
VIN:	4DRBUAAN48B499586			License Number:	B629C
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2008
Inspection Status:	R	Inspected By:	Chuck Tharp	PE:	5618

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
56-1-5	Step-well light is missing or inoperative
14-1-1	The defroster system is not functioning properly.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.