

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|------------------------------|------------------------|-------------|-------------------------|-----------|
| Type of Inspection: | Annual | Date: | 6/18/2013 | Time: | 9:05 AM |
| Name of School Corporation: | ST JOHN LUTHERAN SCHOOL (57) | Corp ID: | 220024 | | |
| Address of School Corporation: | 301 S Oak Street | | | | |
| City: | Kendallville | Zip: | 46755 | County Number: | 57 |
| VIN: | 1GBHG31V541195656 | License Number: | B826A | Bus Number: | 1 |
| Make of Body: | Collins Bus Corporation | Year: | 2004 | Make of Chassis: | Chevrolet |
| Bus Type: | A1 | Mileage: | Unknown | | |
| Inspection Status: | R | Inspected By: | Brian Bills | PE: | 5506 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 22-1-3 | An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.