

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/18/2013	Time:	9:05 AM	
Name of School Corporation:	ST JOHN LUTHERAN SCHOOL (57)	Corp ID:	220024			
Address of School Corporation:	301 S Oak Street					
City:	Kendallville	Zip:	46755	County Number:	57	
VIN:	1GBHG31V541195656	License Number:	B826A	Bus Number:	1	
Make of Body:	Collins Bus Corporation	Year:	2004	Make of Chassis:	Chevrolet	
Bus Type:	A1	Mileage:	Unknown			
Inspection Status:	R	Inspected By:	Brian Bills		PE:	5506

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.