

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/18/2013	<b>Time:</b> 8:44 AM
<b>Name of School Corporation:</b> SHELBYVILLE CENTRAL SCHOOLS	<b>Corp ID:</b> 737365	
<b>Address of School Corporation:</b> 803 St Joseph St		
<b>City:</b> Shelbyville	<b>Zip:</b> 46176	<b>County Number:</b> 73
<b>VIN:</b> IHVBBABP4XH201800	<b>License Number:</b> B254E	<b>Bus Number:</b> 9
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 1999	<b>Mileage:</b> Unknown	<b>Year:</b> 1999
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
19-1-3	The handle guard is missing or bent.
54-1-4	Turn stops are missing or improperly adjusted
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
45-1-2	Seat back or bottom is loose.
40-1-4	There is debris in the bus. (needs cleaned) includes dirt

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**