REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Registration		Date:	7/8/2013	Time:	11:51 AM
Name of School Co	orporation:	DELAWARE COMM.	SCHOOL CORP.		Corp ID:	181875
Address of School	Corporation:	7821 SR 3 N				
City:	Muncie	Zip:	47303		County Number:	18
VIN:	4DRBUAAN5E	B778959	License Number:	6136	Bus Number:	1324
Make of Body:	IC Corporation	Year: 2014	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	Jamie Hotchkiss		PE:	6458

Violations - Rejected

Inspection Code	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
43-1-1	Marker light or lens is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.