

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/16/2013	<b>Time:</b> 10:19 AM
<b>Name of School Corporation:</b> BETHANY CHRISTIAN SCHOOLS	<b>Corp ID:</b> 20B015	
<b>Address of School Corporation:</b> 2904 S Main St		
<b>City:</b> Goshen	<b>Zip:</b> 46526	<b>County Number:</b> 20
<b>VIN:</b> 1GB3G2BG1B1110703	<b>License Number:</b> B914F	<b>Bus Number:</b> MB6
<b>Make of Body:</b> Star Trans	<b>Year:</b> 2011	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2010	<b>Mileage:</b> Unknown	
<b>Bus Type:</b> B		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Brian Bills	<b>PE:</b> 5506

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
19-1-8	If required, positive door opening device is missing or fails to operate properly.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**