

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 7/25/2013 Time: 8:55 AM  
Name of School Corporation: SOUTHWESTERN CON SCH SHELBY CO Corp ID: 737360  
Address of School Corporation: 3406 W 600 S  
City: Shelbyville Zip: 46176 County Number: 73  
VIN: 1FDPB80C7TVA19732 License Number: B791D Bus Number: 10  
Make of Body: Carpenter Year: 1997 Make of Chassis: Ford Year: 1997  
Bus Type: C Mileage: Unknown  
Inspection Status: O Inspected By: Chris Clark PE: 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
45-1-1	Seat is loose from the floor or seat rail.
39-1-2	Required instrument or gauge is inoperative.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord
61-2-1	Two (2) or more taillights or brake lights do not function
45-2-2	Seat is broken or not attached to the floor.

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.