

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/25/2013 **Time:** 8:55 AM
Name of School Corporation: SOUTHWESTERN CON SCH SHELBY CO **Corp ID:** 737360
Address of School Corporation: 3406 W 600 S
City: Shelbyville **Zip:** 46176 **County Number:** 73
VIN: 1FDPB80C7TVA19732 **License Number:** B791D **Bus Number:** 10
Make of Body: Carpenter **Year:** 1997 **Make of Chassis:** Ford **Year:** 1997
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
45-1-1	Seat is loose from the floor or seat rail.
39-1-2	Required instrument or gauge is inoperative.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord
61-2-1	Two (2) or more taillights or brake lights do not function
45-2-2	Seat is broken or not attached to the floor.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.