## REPORT OF SCHOOL BUS INSPECTION

Type of 11:04 7/31/2013 **Time**: Annual Date: Inspection: AM Name of School Corporation: **AVON COMMUNITY SCHOOLS** Corp ID: 323315 7203 E HWY 36 **Address of School Corporation:** County City: Avon Zip: 46123 32 Number: License VIN: 4UZAAXDCX5CN93625 20395 **Bus Number:** Number: Make of Thomas Built Buses, Year: 2005 Freightliner Year: Make of Body: 2005 Inc. Chassis: **Bus Type:** С Mileage: Unknown Inspection Inspected R PE: **Edwin Davis** 3981 Status: By:

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

Washers do not function properly in any manner

36-1-1 The horn does not operate at all.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.