

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/1/2013	Time: 9:32 AM
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315	
Address of School Corporation: 7203 E HWY 36		
City: Avon	Zip: 46123	County Number: 32
VIN: 4DRBUAAN16B235674	License Number: 13391	Bus Number: 13
Make of Body: IC Corporation	Year: 2006	Make of Chassis: IC Corporation
Year: 2006	Mileage: Unknown	PE: 6196
Bus Type: C	Inspected By: John Pang	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.