REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:RegistrationDate:8/1/2013Time:1:16 PMName of School Corporation:NORTH VERMILLION COMM SCH CORPCorp ID:838010

Address of School Corporation: 5551 N Falcon Dr

City:CayugaZip:47928County Number:83VIN:4DRBUAAN4BB333088License Number:Bus Number:10Make of Body:IC Corporation Year:2011Make of Chassis:IC Corporation Year:2011

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Chuck Tharp PE: 5618

Violations - Rejected

Inspection Code	<u>Description</u>
67-1-1	Washers do not function properly in any manner
73-1-1	The anti-vandalism device fails to operate.
28-1-5	Prohibited area sign is missing or obscured.
28-1-4	Prohibited area line is missing or improper.

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

64-2-1 Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.