REPORT OF SCHOOL BUS INSPECTION

Type of 9:48 8/6/2013 Time: Re-Inspection Date: Inspection: AM Name of School Corporation: **AVON COMMUNITY SCHOOLS** Corp ID: 323315 7203 E HWY 36 **Address of School Corporation:** County City: Avon Zip: 46123 32 Number: License VIN: 4UZAAXAK33CK78772 18975 **Bus Number:** 83 Number: Make of Thomas Built Buses, Year: 2003 Freightliner Year: Make of Body: 2003 Inc. Chassis:

Bus Type: C

Inspection Status: R Inspected By: John Pang PE: 6196

Mileage:

Unknown

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

21-1-1 A dripping oil or fluid leak.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.