

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 9/6/2013 **Time:** 10:48 AM
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL **Corp ID:** 161655
Address of School Corporation: 1645 W SR 46
City: Greensburg **Zip:** 47240 **County Number:** 16
VIN: 1FDP880C7SYA48078 **License Number:** B555D **Bus Number:** 16
Make of Body: Ford **Year:** 1995 **Make of Chassis:** Ford **Year:** 1995
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-4	Trim color is other than black.
23-1-1	The bus body has rust or rusted through areas which may weaken the body.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
13-2-2	Crossmember is rusted sufficiently to weaken floor supports.
13-2-1	Crossmember is cracked or broken

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.