

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/6/2013	Time:	9:59 AM
Name of School Corporation:	DECATUR COUNTY COMM. SCHOOL			Corp ID:	161655
Address of School Corporation:	1645 W SR 46				
City:	Greensburg	Zip:	47240	County Number:	16
VIN:	1HVBBAAN9SH251651			License Number:	Bus Number: 11
Make of Body:	IC Corporation	Year:	1995	Make of Chassis:	IC Corporation Year: 1995
Bus Type:	C			Mileage:	Unknown
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
61-1-3	The size and/or placement of brake or taillights do not conform to State School Bus Committee specifications
23-1-1	The bus body has rust or rusted through areas which may weaken the body.
50-1-1	Door seals are missing, damaged, or torn.
19-1-4	Rubber seals are missing or loose.
19-1-2	Excessive effort is needed to open the emergency door.
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
13-2-2	Crossmember is rusted sufficiently to weaken floor supports.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.