## REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual Date: 9/6/2013 **Time**: 8:46 AM Inspection: Name of School Corporation: DECATUR COUNTY COMM. SCHOOL 161655 Corp ID: **Address of School Corporation:** 1645 W SR 46 County City: Greensburg Zip: 47240 16 Number: VIN: 1GBL7T1P3SJ111956 License Number: B953C **Bus Number:** Make of Blue Bird Make of Body: **Year:** 1995 Chevrolet Year: 1995 Corporation Chassis:

C Mileage: Unknown

Inspection Status: R Inspected By: Chris Clark PE: 6665

## Violations - Rejected

**Bus Type:** 

Inspection Code Description

- The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
- 22-1-3 An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.