

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/5/2013	Time:	10:24 AM		
Name of School Corporation:	DECATUR COUNTY COMM. SCHOOL			Corp ID:	161655		
Address of School Corporation:	1645 W SR 46						
City:	Greensburg	Zip:	47240	County Number:	16		
VIN:	1HVBABP2VH466860		License Number:	B553D	Bus Number:	17	
Make of Body:	IC Corporation	Year:	1997	Make of Chassis:	IC Corporation	Year:	1997
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
68-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
61-1-2	One (1) taillight or one (1) brake light does not function
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-5	There is brake fluid leaking at any point.
64-2-1	Warning lights fail to operate correctly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.