

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 9/9/2013	Time: 8:12 AM	
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL	Corp ID: 161655		
Address of School Corporation: 1645 W SR 46			
City: Greensburg	Zip: 47240	County Number: 16	
VIN: 1HTBBAAN5SH219417	License Number: B843D	Bus Number: 4	
Make of Body: IC Corporation	Year: 1995	Make of Chassis: IC Corporation	Year: 1995
Bus Type: C	Mileage: Unknown		
Inspection Status: R	Inspected By: Chris Clark	PE: 6665	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-1	The bus body has rust or rusted through areas which may weaken the body.
38-1-1	There is evidence of damage or rust-through.
14-1-2	A defroster motor is inoperative at any speed.
40-1-4	There is debris in the bus. (needs cleaned) includes dirt

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.