REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual Date: 9/20/2013 Time: 10:56 AM

Name of School Corporation: HANOVER COMM. SCHOOL CORP. Corp ID: 454580

Address of School Corporation: PO Box 645

Corporation

City: Cedar Lake Zip: 46303 County Number: 45
VIN: 1HVBBABN11H356410 License Number: 17933 Bus Number: 15

Make of Body: Comparation Year: 2001

Make of Chassis: IC Corporation Year: 2001

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Nathan Sherer PE: 7029

Violations - Rejected

Inspection

<u>Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
45-1-1	Seat is loose from the floor or seat rail.
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Paint is badly faded or peeling.

Violations - Out of Service

Inspection Code Description

54-2-5 There is movement in a spring loaded drag link greater than 1/8 inch

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.