

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/26/2013	Time:	9:24 AM
Name of School Corporation:	MOORESVILLE CONS. SCHOOL CORP.	Corp ID:	555930		
Address of School Corporation:	173 Indianapolis Rd				
City:	Mooresville	Zip:	46158	County Number:	55
VIN:	1BABKCKH47F239463	License Number:	30308	Bus Number:	46
Make of Body:	Blue Bird Corporation	Year:	2007	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Mark Raper	PE:	6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
56-1-2	Step-well area is weakened
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
63-1-4	Front turn signal does not function properly
63-1-2	A lens is cracked, missing or wrong color
67-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
69-2-1	Glass or glazing is broken through or missing
56-2-1	Part of the step-well or support structure is rusted through
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
54-2-3	Any steering component jams or inhibits safe movement

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus,

behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.