

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/3/2013	Time:	10:15 AM
Name of School Corporation:	TRI-CAP EOC, INC			Corp ID:	19001Z
Address of School Corporation:	PO Box 729				
City:	Jasper	Zip:	47546	County Number:	19
VIN:	1GBHG31K1RF156868			License Number:	13931
Make of Body:	Blue Bird Corporation	Year:	1994	Make of Chassis:	Chevrolet
Bus Type:	A1			Year:	1994
Inspection Status:	O	Inspected By:	Kelly Hammond	PE:	6682

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
27-1-2	The first aid kit is not properly filled.

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.