

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/21/2013	Time:	11:45 AM
Name of School Corporation:	EAST NOBLE SCHOOL CORPORATION			Corp ID:	576060
Address of School Corporation:	126 W Rush St				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	1HVBBABPX2H547942	License Number:	18638	Bus Number:	23
Make of Body:	IC Corporation	Year:	2003	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	Unknown	Year:	2003
Inspection Status:	O	Inspected By:	Brian Bills	PE:	5506

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Front turn signal does not function properly
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
21-1-1	A dripping oil or fluid leak.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
52-2-1	Broken main leaf in a leaf spring.
30-2-1	Frame is deteriorated, cracked, broken or severely bent.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.