

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 10/21/2013      **Time:** 11:45 AM  
**Name of School Corporation:** EAST NOBLE SCHOOL CORPORATION      **Corp ID:** 576060  
**Address of School Corporation:** 126 W Rush St  
**City:** Kendallville      **Zip:** 46755      **County Number:** 57  
**VIN:** 1HVBABPX2H547942      **License Number:** 18638      **Bus Number:** 23  
**Make of Body:** IC Corporation      **Year:** 2003      **Make of Chassis:** IC Corporation      **Year:** 2003  
**Bus Type:** C      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Brian Bills      **PE:** 5506

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Front turn signal does not function properly
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
21-1-1	A dripping oil or fluid leak.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
52-2-1	Broken main leaf in a leaf spring.
30-2-1	Frame is deteriorated, cracked, broken or severely bent.

### Bus Type Description

**Type C School Bus** - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.