

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/25/2013 **Time:** 12:03 PM
Name of School Corporation: NEW PRAIRIE UNITED SCH CORP **Corp ID:** 464805
Address of School Corporation: 5327 N Cougar Rd
City: New Carlisle **Zip:** 46552 **County Number:** 46
VIN: 4DRBUAANXDB309171 **License Number:** 4754 **Bus Number:** 54
Make of Body: IC Corporation **Year:** 2013 **Make of Chassis:** IC Corporation **Year:** 2013
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** David Eggers **PE:** 5191

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
49-2-1	There is no seat belt cutter in the vehicle.
7-2-1	There is no brake certification, the certification is expired, or is not signed within the six-month requirement.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.