REPORT OF SCHOOL BUS INSPECTION

Type of Post-Crash Inspection Date: 10/25/2013 Time: 12:03 PM

Name of School Corporation: NEW PRAIRIE UNITED SCH CORP Corp ID: 464805

Address of School Corporation: 5327 N Cougar Rd

City: New Carlisle Zip: 46552 County Number: 46
VIN: 4DRBUAANXDB309171 License Number: 4754 Bus Number: 54

Make of Body: Year: 2013 Make of Chassis: IC Corporation Year: 2013

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: David Eggers PE: 5191

Violations - Rejected

Inspection Code Description

The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

Inspection Code	<u>Description</u>
49-2-1	There is no seat belt cutter in the vehicle.
7-2-1	There is no brake certification, the certification is expired, or is not signed within the six-month requirement.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.