REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:10/28/2013Time:9:17 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1HVBBABP2YH283639License Number:Bus Number:7Make of Body:AmTranYear:2000Make of Chassis:IC CorporationYear:2000

Bus Type: C Mileage: Unknown

Inspection Status: A Inspected By: Travis Coryea PE: 5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.