

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks	Date: 11/1/2013	Time: 8:43 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 4DRBUSKN69B095307	License Number: 30874	Bus Number: 22
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation
Year: 2009	Mileage: Unknown	Year: 2009
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.