REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	11/8/2013	**Time:**	3:37 PM
Name of School Corporation:		ANDERSON COMM. SCHOOL CORP.				**Corp ID:**	485275
Address of School Corporation:		1600 Hillcrest Ave					
City:	Anderson	**Zip:**	46011			**County Number:**	48
VIN:	1hvbvabp9wh569985			**License Number:**	33	**Bus Number:**	33
Make of Body:	Blue Bird Corporation	**Year:**	1999	**Make of Chassis:**	IC Corporation	**Year:**	1999
Bus Type:	C			**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**		Jeremy Mason		**PE:**	8139

Violations - Rejected

Inspection Code	Description
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
63-1-4	Front turn signal does not function properly
20-1-1	A belt is badly chaffed, cracked, broken or missing.

Violations - Out of Service

Inspection Code	Description
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
24-2-2	Reflective glass is cracked, broken, or missing.
33-2-1	Both lamps are inoperative on low beam.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.