

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|--------------|-------------------------|-----------------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 12/2/2013 | Time: | 1:36 PM |
| Name of School Corporation: | MARION COMMUNITY SCHOOLS | Corp ID: | 272865 | | |
| Address of School Corporation: | 826 E 30th St | | | | |
| City: | Marion | Zip: | 46952 | County Number: | 27 |
| VIN: | 1BAKJCPA5AF274471 | License Number: | 74380 | Bus Number: | 11 |
| Make of Body: | Blue Bird Corporation | Year: | 2010 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | C | Mileage: | Unknown | Year: | 2010 |
| Inspection Status: | O | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 45-1-5 | Upholstery or padding is ripped, torn, or improperly repaired. |
| 4-1-1 | Any body clamp is loose. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-2-1 | There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.). |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.