

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 12/3/2013	<b>Time:</b> 11:25 AM
<b>Name of School Corporation:</b> ILLINOIS CENTRAL SCHOOL BUS	<b>Corp ID:</b> 45015Z	
<b>Address of School Corporation:</b> 801 E Main		
<b>City:</b> Griffith	<b>Zip:</b> 46319	<b>County Number:</b> 45
<b>VIN:</b> 4UZABRDD08CZ11242	<b>License Number:</b> B356E	<b>Bus Number:</b> 575
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2008	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2008	<b>Mileage:</b> Unknown	<b>Year:</b> 2008
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Nathan Sherer	<b>PE:</b> 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
27-1-2	The first aid kit is not properly filled.
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
45-1-2	Seat back or bottom is loose.
79-1-3	If equipped, the emergency warning buzzer does not sound.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
8-2-1	There is no brake certification, the certification has expired, or is not signed within the six month requirement.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**